

# LIMITED WARRANTY AND LIMITATION OF LIABILITY

Customers enjoy one-year warranty from the date of purchase.

This warranty does not cover fuses, disposable batteries, damage from misuse accident, neglect, alteration, contamination, or abnormal conditions of operation or handling, including failures caused by use outside of the product's specifications, or normal wear and tear of mechanical components.

# **Table of Contents**

Introduction	1
Safety Information	.1
Instrument Overview	3
LCD Display	3
Function Buttons	
Rotary Switch	7
Input Terminals	
Measurements Instruction	12
Measure AC/DC Voltage	12
Measure AC/DC Current	12
Measure Resistance	13
Test for Continuity	14
Test Diodes	14
Measure Capacitance	15
Measure Frequency	16
Measure Duty Cycle	16
Measure Temperature	

## Page

Square waves output	17
Battery measurement	17
NCV	18
V.F.C	18
Maintenance	19
Clean the Product	19
Replace the Batteries	19
Replace the Fuses	20
Specifications	21
General Specifications	21
Mechanical Specifications	21
Environmental Specifications	22
Electrical Specifications	23

## Introduction

This product is a battery-powered, true-rms, autoranging digital multimeter with a 6000 counts LCD display and a backlight.

## **Safety Information**

To avoid possible electrical shock, fire, or personal injury, please read all safety information before you use the product. Please use the product only as specified, or the protection supplied by the product can be compromised.

- Examine the case before you use the product. Look for cracks or missing plastic. Carefully look at the insulation around the terminals.
- The measurement must be made with correct input terminals and functions and within the allowable measuring range.

- Do not use the product around explosive gas, vapor, or in damp or wet environments.
- Keep fingers behind the finger guards on the probes.
- When the product has already been connected to the line being measured, do NOT touch the input terminal that is not in service.
- Disconnect the test leads from the circuit before changing the mode.
- When the voltage to be measured exceeds 36V DC or 25V AC, the operator shall be careful enough to avoid electric shock.
- Misuse of mode or range can lead to hazards, be cautious. " []L" will be shown on the display when the input is out of range.
- Low level of a battery will result in incorrect readings. Change the batteries when battery level is low. Do not make measurements when the battery door is not properly placed.

## **Instrument Overview**

LCD Display				
1	AUTO	Auto range. The product selects the range with the best resolution		
2	MANUAL	Manual range. The user selects the range. The product measures both sinusoidal and nonsinusoidal ac waveforms accurately. Display freezes present reading		
3	REL			
4	HOLD			
5	MAX	Display shows maximum reading.		
6	▶	Diode test. Display shows minimum reading. Continuity test.		
$\bigcirc$	MIN			
8	111)			


9	V.F.C	Voltage Frequency Converter			
(10)	-8.8.8.8	Secondary measurements display			
(11)	%	Duty cycle test.			
(12)	໊Բ໊Ը	Temperature test. (Fahrenheit or Celsius)			
(13)	Hz	Frequency test. (Hertz)			
14)	໊Բ໊Ը	Temperature test. (Fahrenheit or Celsius)			
(15)		Analog bar graph.			
16	T-RMS	The product measures both sinusoidal and nonsinusoidal ac waveforms accurately.			
(17)	-8.8.8.8	Primary measurement display.			
(18)	Û	Low battery. Replace batteries.			
(19)	AC	Alternating current.			
20	20 DC Direct current.				
nk	Moom	Measurement units.			

### **Function Buttons**

11	RANGE V.F.C OFF NCV		
1	<ul> <li>Selects alternate measurement modes on a rotary switch setting, including:</li> <li>1. Frequency/AC V</li> <li>2. Frequency/AC mV</li> <li>3. DC A/AC A</li> <li>4. DC mA/AC mA</li> <li>5. DC μA/AC μA</li> <li>6. Square waves output</li> </ul>		
2	Push once to hold the current reading on the display; push again to continue normal operation.		

3	Push this button once to enter the manual range mode. In manual range mode, each push increases the range; when the highest range is reached, the next push will lead to the lowest range. To exit the manual range mode, Long push for exit.			
4	Push this button once to enter the V.F.C model. Push once more to exit the model.			
5	Push this button to enter the relative mode. The product will store the present reading as a reference for subsequent readings. The display is zeroed, and the stored reading is subtracted from all subsequent readings. Push again to exit the relative mode. Push this button over 2 seconds, it will open the flashlight, long push again to turn off the flashlight			
6	Push to toggle between the MAX and the MIN mode. To exit MAX/MIN mode, push the button for more than 2 seconds			

### **Rotary Switch**




	<ul> <li>Turn off the product at this position.</li> <li>The product automatically powers off after 15 minutes of inactivity.</li> <li>The built-in beeper beeps 5 times 1 minute before auto power off.</li> <li>To restart the product from auto</li> </ul>
OFF	1 minute before auto power off.

<sup>%</sup> V.F.C H₂ V	AC V≤750V, Frequency V.F.C			
V	DC V≤1000V			
<sup>™</sup> mV	ACV (mV) ≤800.0mV Frequency (Equal to <sup>%</sup> Hz )			
mV	DC V (mV) ≤800.0mV			
<sup>%</sup> Hz	Frequency, Duty cycle: 1%~99%。			
Ω	Resistance: $\leq 80M \Omega$ .			
⊣⊢	Capacitance: <100mF.			
*	Diode			
-1))	Continuity			
Ā	DC A: ≤20A。 AC A: ≤20A。			
mĀ	DC A: ≤800.0mA. AC A: ≤800.0mA.			
μĂ	DC A: ≤800.0 μ A. AC A: ≤800.0 μ A.			
°F°C	Celsius:-20~1000, Fahrenheit:- 4~1832			

8 <u>.</u>	DC V: ≤8V		
80V	DC V: ≤80V		
800V	DC V: ≤800V		
1000V	DC V: ≤1000V		
750V	AC V: ≤750V		
80V	AC V: ≤80V		
8V	AC V: ≤8V		
80MΩ	Resistance: ≤80MΩ		
8MΩ	Resistance: ≤8MΩ		
800KΩ	Resistance: ≤800KΩ		
80KΩ	Resistance: ≤80KΩ		
8KΩ	Resistance: ≤8KΩ		
800Ω	<b>Resistance:</b> $\leq 800 \Omega$		
12V 1	12V Battery test		
90	9V Battery test		
1.5V	1.5V Battery test		

NCV Non-contact Voltage	201



20A	Input terminal for AC/DC current measurements to 20A.				
mA μA	Input terminal for AC/DC current measurements to 800mA. Input terminal for battery testing.				
СОМ	Common (return) terminal for all measurements.				
<del>⊁</del> .⊪.Ձ VΩHz-⊩	Input terminal for the measurements of: 1. AC/DC voltage 2. Resistance 3. Capacitance 4. Frequency 5. Temperature 6. Continuity 7. Diode 8. Duty cycle 9. Square waves output				

## **Measurements Instruction**

### Measure AC/DC Voltage

- Connect the black test lead to the COM Terminal and the red lead to the VQHz++ Terminal.
- Turn the rotary switch to each manual range from 8V~1000V according to the votage you want to test. Or you can choose the auto-range for testing the voltage.
- 3. Touch the probes to the correct test points of the circuit to measure the voltage.
- 4. Read the measured voltage on the display.

\*Do not measure voltage that exceeds the extremes as indicated in the Specifications.

\*Do not touch high voltage circuit during measurements.

#### Measure AC/DC Current

 Connect the black test lead to the COM Terminal and the red lead to the mA μA (MAX current is 800mA)Terminal or the 20A (MAX current is 20A)Terminal (choose based on the value of the current to be measured).

- Turn the rotary switch t A mA , A according to the signal you want to test.
- 3. Press SELECT to toggle between AC/DC.
- 4. Break the circuit path to be measured, connect the test leads across the break and apply power.
- 5. Read the measured current on the display.

\*Do not measure current that exceeds the extremes as indicated in the Specification ₹.

\*Use the 20A Terminal and the Mode when you are measuring an unknown currer <sup>™</sup><sub>№</sub> Then switch <sup>™</sup><sub>№</sub> the mA µA Terminal and the Mode or the Mode if necessary.

\*Do not input voltage at this setting.

#### Measure Resistance

- Connect the black test lead to the COM Terminal and the test lead to the VORANT Terminal.
- Turn the rotary switch to each range from 800 Ω<sup>~</sup>80M Ω, Or you can tuen the rotaty switch to Ω model.
- Touch the probes to the desired test points of the circuit to measure the resistance.
- 4. Read the measured resistance on the display.

\*Disconnect circuit power and discharge all capacitors before you test resistance. \*Do not input voltage at this setting.

### **Test for Continuity**

- Connect the black test lead to the COM Terminal and the red lead to the VORTH Terminal.
- 2. Turn the rotary switch to <u>M</u>.
- Touch the probes to the desired test points of the circuit.
- 4. The built-in beeper will beep when the resistance is lower than  $50\Omega$ , which indicates a short circuit.

#### \*Do not input voltage at this setting.

### **Test Diodes**

1. Connect the black test lead to the COM Terminal and the red lead to the VORTH Terminal.

- 2. Turn the rotary switch to 🗲,
- Connect the red probe to the anode side and the black probe to the cathode side of the diode being tested.
- 4. Read the forward bias voltage value on the display.
- If the polarity of the test leads is reversed with diode polarity or the diode is broken, the display reading shows " []L".

\*Do not input voltage at this setting. \*Disconnect circuit power and discharge all capacitors before you test diode.

#### Measure Capacitance

- Connect the black test lead to the COM Terminal and the red lead to the \*\*\*\*\*\* Terminal.
   Turn the reter outline to Terminal.
- 3. Connect the red probe to the anode side and

the black probe to the cathode side of the capacitor being tested.

4. Read the measured capacitance value on the display once the reading is stablized.

\*Disconnect circuit power and discharge all capacitors before you test capacitance.

### Measure Frequency

- Connect the black test lead to the COM Terminal and the red lead to the tothe Terminal.
- Turn the rotary switch to <sup>%</sup>Hz (applies to high frequency with low voltage); or turn the rotary switch to <sup>%</sup>, press SELECT once to toggle to the Frequency Mode (applies to low frequency with high voltage).
- 3. Touch the probes to the desired test points.
- 4. Read the measured frequency value on the display.

### Measure Duty Cycle

- Connect the black test lead to the COM Terminal and the red lead to the VORCH Terminal.
- Turn the rotary switch to <sup>%</sup>Hz, press the Hz % button once to toggle to the Duty Cycle Mode.
- 3. Touch the probes to the desired test points.
- 4. Read the measured duty cycle value on the display.

#### Measure Temperature

- Connect the black thermocouple probe to the COM Terminal and the red probe to the \*\* 470.4 VOHer# Terminal.
- Turn the rotary switch to <sup>P</sup>C, and the display will show the room temperature, to toggle between <sup>°</sup>C/<sup>°</sup>F, press SELECT button.
- 3. Touch the probes to the desired test points.
- 4. Read the measured temperature on the display.

### \*Do not input voltage at this setting.

### Square Wave Output

- Connect the black test lead to the COM Terminal and the red lead to the Valuet Terminal.
- Turn the rotary switch to me , and the default output frequency is 50Hz. To change the output frequency, press the SEL button.
- 3. Touch the probes to the desired test points.

#### \*Do not input voltage at this setting.

#### **Battery Measurement**

- Connect the red lead into the mAµA terminal, and the black lead into the COM terminal.
- When you test the batteries, You can change the range between 1.5v, 9v, and 12v.

Battery test	1. 5V	9V	12V
load Current	10mA	10mA	10mA

 Connect the probes to the positive and negative poles of the battery, then you can read the voltage on the screen. Or you can judge the voltage according to the color of central lighting

#### Test NCV

- 1. Keep pushing the NCV button .
- Hold the product and move it around, the builtin beeper will beep when the inner sensor detects AC voltage nearby. The stronger the voltage is, the quicker the beeper beeps.

### Test V.F.C

- 1, Connect the black test lead to the COM Terminal and the red lead to the "dMath Terminal
- Turn the rotary switch to , push once to enter the V.F.C mode. Touch the probes to the desired test points, read the voltage on display.

## Maintenance

Beyond replacing batteries and fuses, do not attempt to repair or service the product unless you are qualified to do so and have the relevant calibration, performance test, and service instructions.

#### **Clean the Product**

Wipe the product with a damp cloth and mild detergent. Do not use abrasives or solvents. Dirt or moisture in the terminals can affect readings. \*Remove the input signals before you clean the product.

### **Replace the Batteries**

When " T is shown on the display, batteries shall be replaced as below:

1. Remove the test leads and turn off the product before replacing the batteries.

- 2. Loosen the screw on the battery door and remove the battery door.
- 3. Replace the used batteries with new batteries of the same type.
- 4. Place the battery door back and fasten the screw.

### **Replace the Fuses**

When a fuse is blown or do not work properly, it shall be replaced as below:

- 1. Remove the test leads and turn off the product before replacing the fuse.
- Loosen the four screws on the back cover and the screw on the battery door, then remove the battery door and the back cover.
- 3. Replace the fuse with a new fuse of the same type.
- 4. Place the back cover and the battery door back and fasten the screws.

# **Specifications**

General Specifications				
Display (LCD)		8000 counts		
Ranging	Ranging		to/Manual	
Material		ABS/PVC		
Update Rate	Update Rate		3 times/second	
Ture RMS		V		
Data Hold		V		
Backlight		N N		
Low Battery Indication		V		
Auto Power Off		201	V	
Mechanical Specifications				
Dimension	1		6*91*47mm	
Weight		330g		
Battery Type		1.5V AA Battery * 3		
Warranty			One year	
Environmental Specifications				
Operating	Temperature		0~40°C	
	Humidity		<75%	
Storage	Temperature		-20~60°C	
	Humidity		<80%	

## **Electrical Specifications**

Function	Range	Resolution	Accuracy
DC Voltage (V) (mV)	800.0mV	0.1mV	±(0.5%+3)
	8.000V	0.001V	
	80.00V	0.01V	
	800.0V	0.1V	
	1000V	1V	
AC Voltage (V) (mV)	800.0mV	0.1mV	±(1.0%+3)
	8.000V	0.001V	
	80.00V	0.01V	
	750V	1V	
DC Current (A)	8.000A	0.001A	1/1 20/12)
	20.00A	0.01A	±(1.2%+3)

Function	Range	Resolution	Accuracy
DC Current (mA)	8.000mA	0.001mA	
	80.00mA	0.01mA	
	800.0mA	0.1mA	±(1.2%+3)
DC Current	800.0µA	0.1µA	655
(μA)	8000µA	1μΑ	a Col
AC Current (A)	8.000A	0.001A	NY EX
	20.00A	0.01A	P.
AC Current (mA)	8.000mA	0.001mA	
	80.00mA	0.01mA	±(1.5%+3)
	800.0mA	0.1mA	
AC Current (μA)	800.0µA	0.1µA	
	8000µA	1μΑ	
Resistance	800.0Ω	0.1Ω	
	8.000kΩ	0.001kΩ	
	80.00kΩ	0.01kΩ	±(0.5%+3)
	800.0kΩ	0.1kΩ	
	8.000MΩ	0.001MΩ	
	80.00MΩ	0.01MΩ	±(1.5%+3)

Function	Range	Resolution	Accuracy	
Capacitance	9.999nF	0.001nF	±(5.0%+20)	
	99.99nF	0.01nF		
	999.9nF	0.1nF	~	
	9.999µF	0.001µF	±(2.0%+5)	
	99.99µF	0.01µF	SPEPT	
	999.9µF	0.1µF	SI II	
	9.999mF	0.001mF		
	99.99mF	0.01mF	±(5.0%+5)	
Frequency	9.999Hz	0.001Hz		
	99.99Hz	0.01Hz		
	999.9Hz	0.1Hz	±(0.1%+2)	
	9.999kHz	0.001kHz		
	99.99kHz	0.01kHz		
	999.9kHz	0.1kHz		
	9.999MHz	0.001MHz		
Duty Cycle	1%~99%	0.1%	±(0.1%+2)	

Function	Range	Resolution	Accuracy	
Temperature	(-20~1000)°C	1°C		
	(-4~1832)°F	1°F	±(2.5%+5)	
Diode	V			
Continuity	V			
Square wave output	50Hz~5000Hz			

