


C110+,C310+,C200,C100 S 升级流程

1 step: download update tool and update Date, as show:

website: [www.szcreator.com](http://www.szcreator.com)

if you had installed the update tool, you only need to download the update date.



Click [ DOWNLOAD ], and select the update date which do you update

C200_OBD_V5.7	English, Chinese, German, Spanish, Dutch, Russian
OS601 software	
OS601_OBD_V10.7	English, Chinese, German, Spanish, Dutch, Russian
C300 software	
C300_OBD_V4.3_CN	English, Chinese, German, Spanish
C310 software	
C310_BMW_V6.6_DE	German
C310_BMW_V6.6_EN	English
C310_BMW_V6.6_HK	Traditional Chinese
C310+ software	
C310+_BMW_V8.0_DE	German
C310+_BMW_V8.0_EN	English
C310+_BMW_V8.0_HK	Traditional Chinese
C310+_BMW_V8.0_CN	Chinese
C330 software	
C330_V1.1_CN	Chinese
C110+, C310+, C200 update tool	
C1XX, C3XX, C2XX update tool	fix to C100, C110+, C200, OS601, C300, C310+, C330
C50X update tool	
C50X update tool	fix to C500, C501, C502, C503, C508

升级数据包，不用设备下载相应的数据包

升级工具安装包

Update tool download:


新建下载任务

网址: [http://pmo76fd5f.pic20.websiteonline.cn/upload/UpdateTool\\_V3.rar](http://pmo76fd5f.pic20.websiteonline.cn/upload/UpdateTool_V3.rar)

名称: **UpdateTool\_V3.rar** 压缩文件 2.21 MB

下载到: [浏览](#)

使用迅雷下载 直接打开 下载 取消




新建下载任务

网址:

名称:  压缩文件 4.42 MB


下载到:  剩: 49.77 GB

 使用迅雷下载

1. Unzip the file UpdateTool\_V3.RAR, and run the EXE file, start install



3 step: unzip update date, you will have a BIN file, save this BIN file to PC:



4 step: Use the USB cable connect tools to PC, and run the update tool on PC, as show.  
the update tool will display USB connect, as show :





5 step:: click [UPDATE] , and select the BIN file （ the file is the 3<sup>rd</sup> step file ）， and click [OPEN]



5 step: the update tool will update, and you need to wait for finish.



The question when you update:

1. If there is an error prompt in the upgrade process, please unplug the device, reconnect and do step 5 again
2. If the upgrade is unsuccessful for many times, change a USB port or use a USB hub to transfer it, and then operate step 5 again.